

FieryXF502.txt

Fiery XF 5.0.2

What's new?

Bug fixes

- Fixed increased graininess (which also affected the gray balance) on EFI VUTEk printers when printing with error diffusion (SE1) halftoning
- Reintroduced the Epson SureColor SC-T3000 / SC-T5000 / SC-T7000 printer drivers in 32-bit Fiery XF installations
- Fixed the "user unit" handling of Esko iCut files
- Fixed the incorrect default behavior of the "target tolerance preset" for control wedges in the Fiery XF client
- Fixed the missing output of the Wide Format T660 and T1000 printer drivers
- Fixed an Adobe PDF Print Engine bug that could lead to problems for some (uncommon) PDF jobs
- Fixed an issue where copied jobs would get an "unknown status" when sent from an EFI MIS to Fiery XF
- Fixed delayed status signals if one of multiple Fiery XF servers connected to one EFI VUTEk printer was switched off